






## **BEFORE CONDITIONS**

#### 4th Ave and Atlantic Ave

- Long Crossing (80')
- Subway infrastructure made concrete island construction not possible
- High Crash Intersection
- Vision Zero Priority Area and Corridors





#### 4th Ave At Atlantic, BK

Injury Summary, 2010-2014 (5 Years)

	Total	Severe	Fatalities	KSI
	Injuries	Injuries		
Pedestrian	12	1	0	1
Bicyclist	4	0	0	0
Motor Vehicle Occupant	72	4	0	4
Total	88	5	0	5

Fatalities, 01/01/2010-11/8/2016: None

Source: Fetelities: NYCDOT Injuries: NYSDOT KSI: Persons Killed or Severely Injured

### RUBBER PEDESTRIAN ISLAND


### Installed December 15th, 2016

- 2016 Pilot treatment in NYC
- Quick 3 1/2 hour installation
- Typical Signs on island
- Island screwed directly into asphalt, no excavation
- Can be installed in any weather condition
- No operational changes

#### **Benefits**

- Safer and shorter two-part pedestrian crossing
- Rapid response at Vision Zero area and corridors





Mattresses

BEFORE

# **THANK YOU!**

Questions?













NYC DOT NYC DOT

nyc\_dot

NYC DOT